

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L2	714	cable same measure same mass	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 15:45
L3	4	2 and (electronic circuit) and (external adj connection)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 15:48
L4	7	tensiometer and (electronic circuit) and (external adj connection)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 15:48
L5	9764	(cable rope thread wire) near3 (grip\$5 clamp\$5 grab\$5 hold45).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 16:13
L6	360	5 and (apply\$5 exert\$5 put\$5) near3 (cable rope thread wire) near3 (pressure compression tensi\$5 force load stress strain).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 16:14
L7	55	6 and ((wire cable thread fiber) near5 (measur\$5 test44 detect\$4 determin\$4 sens\$4 indent\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor comput\$5 inspect\$4 meter calculat\$4)).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 16:16
L8	317	(cylindrical) near5 (cable rope thread wire) near3 (grip\$5 clamp\$5 grab\$5 hold\$4).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 16:17
L9	11	8 and (apply\$5 exert\$5 put\$5) near3 (cable rope thread wire) near3 (pressure compression tens\$5 force load stress strain).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 16:19

L10	16	8 and washer.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 16:20
S1	8	(("2362626") or ("5728953")).PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/20 09:53
S2	24	("1768991" "2362626" "3124770" "3238731" "3284749" "3541844" "3621927" "4019365" "4803888" "4989450").PN. OR ("5728953"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/19 08:31
S3	5	("2362626").URPN.	USPAT	OR	ON	2005/09/19 11:02
S4	189449	cable and (load tension stress strain force)	USPAT	OR	ON	2005/10/03 15:40
S5	19766	(cable and (load tension stress strain force)).clm.	USPAT	OR	ON	2005/09/22 14:00
S6	626	S5 and ("73").clas.	USPAT	OR	ON	2005/09/19 11:03
S13	1206	elevator and mass and cable and (cylinder or cylindrical)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/20 10:10
S14	25	S13 and ("73").CLAS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/20 10:09
S17	248	((73/862.472) or (73/862.392)). CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/22 10:21
S20	129	hanging same mass same cable	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/22 10:25

S22	11	cable same measure same mass same pressure same washer	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 15:45
S23	442	fan same belt and car	USPAT	OR	ON	2005/09/22 15:13
S24	79	S23 and tension	USPAT	OR	ON	2005/09/22 14:00
S25	5	("5345042") or ("5343003") or ("5421433").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/22 16:07
S26	941	(187/391).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/22 16:07
S27	12	("2042201" "2306816" "4664229" "5609225" "5747755").PN. OR ("5890564"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/23 11:05
S28	8084	cable and clamp and screw and washer	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/26 09:33
S29	5021	cable and clamp and (screw same washer)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/26 09:33
S30	13	(cable and clamp and (screw same washer)).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/26 10:10
S31	30	(cable and clamp and screw and washer).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/26 11:14

S33	12712	(cable rope thread wire) near3 (grip\$5 grab\$5 hold\$5).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/26 11:16
S34	2369	S33 and (cable rope thread wire) near3 (pressure compression tensi\$5 force load stress strain). clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/26 11:16
S35	422	S33 and (apply\$5 exert\$5 put\$5) near3 (cable rope thread wire) near3 (pressure compression tensi\$5 force load stress strain). clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/26 11:18
S36	95	S35 and ((wire cable thread fiber) near5 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 ident\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter claculate\$4)).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 16:12
S37	5	S36 and cylind\$5 and (washer spacer)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/26 12:28
S38	121849	clamp and (cylinder cylindrical) and screw	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/26 12:29
S39	2433	(clamp and (cylinder cylindrical) and screw).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/27 09:10
S40	2433	(clamp and (cylinder cylindrical) and screw).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/26 14:21

S41	782	S40 and (washer or spacer)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/26 15:25
S42	139	S41 and cable	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 13:34
S43	9	washer near (different varying) near lengths	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/27 09:10
S44	106359	washer same (space separate distance) same (passage fit between through)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 13:36
S45	91489	washer same (space separate distance) same (passage fit between through) and (clamp\$3 hold\$3 grip\$3 grab\$3 pressure)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 13:47
S48	3862	washer same (space separate distance) same (passage fit between through) same cable same (clamp\$3 hold\$3 grip\$3 grab\$3 pressure)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 13:39
S49	1791	washer same (space) same (between) same cable same (clamp\$3 hold\$3 grip\$3 grab\$3 pressure)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 13:41
S50	71	washer near5 different near3 lengths	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 13:46

S51	924	washer near5 (different various varying) near3 (lengths size thickness)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 13:47
S52	556	S51 and (space separate distance) same (passage fit between through) and (clamp\$3 hold\$3 grip\$3 grab\$3 pressure)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 13:48
S53	205	(S51 same (space separate distance) same (passage fit between through)) and (clamp\$3 hold\$3 grip\$3 grab\$3 pressure)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/10/03 15:39